Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	5494	((228/1.1,4.5,102-104,180.5) or (73/827-831,833-835)).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/11/15 16:32
L2	518	wire near bond\$4 and (measur\$4 or monitor\$4 or detect\$4) near (pull or force)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:34
L3	518	(1 or 2) and wire near bond\$4 and (measur\$4 or monitor\$4 or detect\$4) near (pull or force)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:37
L4	170	3 and (clamp\$4 or grip\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:36
L5	39	4 and (clamp\$4 or grip\$4) near wire	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:39
L6	25	5 and pull near (wire or test\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:37
L7	49	4 and (rais\$4 or lift\$4 or pull\$4) near (clamp\$4 or grip\$4 or wire)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:40
L8	41	7 and (program\$6 or software or comput\$4 or cpu or calculat\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:41

L9	41	8 and (time or clock)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:41
L10	6	8 and (feedback or parameter or adjust or adjusta\$5 or adjustment\$2 or chang\$4 or adapt\$4) near (force or load)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2006/11/15 16:43
L11	35	7 and (holder or arm or beam)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:44
L12	2	11 and (holder or arm or beam) near (resilien\$4 or elastic\$6 or deform\$6 or deflect\$5 or spring)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:44
L13	0	12 and strain near (gage or gauge)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2006/11/15 16:46
L14	20	11 and strain near (gage or gauge)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:47
L15	0	7 and (strain near (gage or gauge)) near (clamp\$4 or grip\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:48
L16	0	4 and (strain near (gage or gauge)) near (clamp\$4 or grip\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:48

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	5494	((228/1.1,4.5,102-104,180.5) or (73/827-831,833-835)).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/11/15 16:32
L2	518	wire near bond\$4 and (measur\$4 or monitor\$4 or detect\$4) near (pull or force)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:34
L3	518	(1 or 2) and wire near bond\$4 and (measur\$4 or monitor\$4 or detect\$4) near (pull or force)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:37
L4	170	3 and (clamp\$4 or grip\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR ·	ON	2006/11/15 16:36
L5	39	4 and (clamp\$4 or grip\$4) near wire	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:39
L6	25	5 and pull near (wire or test\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:37
L7	49	4 and (rais\$4 or lift\$4 or pull\$4) near (clamp\$4 or grip\$4 or wire)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:40
L8	41	7 and (program\$6 or software or comput\$4 or cpu or calculat\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:41

L9	41	8 and (time or clock)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:41
L10	6	8 and (feedback or parameter or adjust or adjusta\$5 or adjustment\$2 or chang\$4 or adapt\$4) near (force or load)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:43
L11	35	7 and (holder or arm or beam)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:44
L12		11 and (holder or arm or beam) near (resilien\$4 or elastic\$6 or deform\$6 or deflect\$5 or spring)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:44
L13	0	12 and strain near (gage or gauge)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:46
L14	20	11 and strain near (gage or gauge)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:47
L15	0	7 and (strain near (gage or gauge)) near (clamp\$4 or grip\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:48
L16	0	4 and (strain near (gage or gauge)) near (clamp\$4 or grip\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/11/15 16:48